

NAVICPLA31 EVALUATION AND REPAIR SERVICES (NOV 1996)

Evaluation to include inspection, disassembly and tests required to determine the extent of labor and material needed to restore the Government Furnished Property (GFP) described below to an operable condition. For the purposes of this acquisition, an operable condition is defined as capable of functioning and performing as a new unit without necessarily having the appearance of newness.

Repair Services to include labor and material required to repair and package the FGFP cited herein. Property repaired hereunder shall be in accordance with drawing revision unless otherwise specified. If upon receipt of the order contract such specifications are considered inappropriate, the contractor shall immediately recommend to the cognizant Contracting Officer that the repair work be done in accordance with specifically identified specifications (including drawings) to which such articles were manufactured, and shall not commence the particular work concerned pending directions to be incorporated by modification. Additionally, whenever any specification of the order provides for the use of a specific article or its equivalent, the contractor may use any equivalent. Also, in those instances where specifications permit and it is economically feasible to do so, component parts of the item(s) being repaired shall also be authorized to be repaired. In addition to NSN and P\N markings, repaired units shall be marked with the purchase order number and date of repair in such a manner as to conform with the requirements of Military Standard Identification Marking of U.S. Military Property, MIL-STD-130 current edition (to the maximum extent possible).

The contractor shall determine, in conjunction with the ACO, if the GFP cannot be repaired. Disposition instructions for such property shall be requested from the Post-Award PCO identified in Section G of this award.

NOTE TO CONTRACTOR: UNDER NO CIRCUMSTANCES SHALL THE CONTRACTOR PROCEED WITH THE PERFORMANCE UNDER THIS ORDER/CONTRACT IF THE GOVERNMENT FURNISHED PROPERTY (GFP) RECEIVED (NSN & P/N) DOES NOT EXACTLY MATCH THAT CITED IN THIS ORDER. ALSO, IF THE GFP HAS NOT BEEN RECEIVED WITHIN THIRTY (30) DAYS FROM THE EFFECTIVE DATE OF THIS ORDER/CONTRACT, CONTACT THE POST-AWARD PCO IDENTIFIED IN SECTION G OF THIS AWARD.

SPECIAL ATTENTION IS DIRECTED TO THE NOTICE ATTACHED FOR PREPARATION OF MATERIAL INSPECTION AND RECEIVING REPORT - DD FORM 250.

REPAIR PRICE AVAILABLE: If Block 21 on the DD1155 does not indicate "Ceiling Price" and the Unit Price(s) in Section B of the award (see continuation sheet) does not indicate (EST), the REPAIR PRICE(s) was AVAILABLE to the Government and the funds obligated by this order are the result of negotiation conducted by the PCO and contractor. The amount shown represents the FIRM PRICE to complete repair of the GFP listed in the order

REPAIR PRICE NOT AVAILABLE: If Block 21 on the DD1155 indicates “Ceiling Price” and the Unit Price(s) in Section B of the award (on the continuation sheet) indicates (EST), the REPAIR PRICE was NOT AVAILABLE to the Government and the funds obligated by this order are provided to initiate evaluation and/or repair work which must be finalized and modification issued to the contractor before payment can be made. The contractor shall submit to the ACO a detailed pricing proposal, to include delivery (turn-around time) for repair of the unit(s) cited in the order. The repair proposal is due within thirty (30) days after receipt of GFP or receipt of order, whichever is later. Pending the establishment of finalized prices, the contractor shall not be obligated to incur costs, which exceed the funds listed in this order. The contractor shall not begin repair work on a unit when the cost of repair is reasonably expected to exceed 100% of the most recent selling price to the Government.